

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

| | | |
|------------|--|---|
| Inventor | : S. H. VOLDMAN | <u>Certificate of Corrections Branch</u> |
| Patent No. | : 7,089,530 | Issued: August 8, 2006 |
| Appl. No. | : 10/707,069 | Filed: November 19, 2003 |
| For | : METHODOLOGY FOR PLACEMENT BASED ON CIRCUIT FUNCTION AND LATCHUP SENSITIVITY | |

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner For Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following errors appearing in the printed patent. These errors are apparently the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction.

At column 16, line 8 (claim 12, line 3) of the printed patent, "1/2," should be ---1/2)---. This appeared correctly on page 6, line 9 of the Amendment Under 37 C.F.R. § 1.111 filed January 5, 2006.

At column 16, line 61 (claim 16, line 19) of the printed patent, "injection" should be ---injection---. This appeared correctly on page 7, line 9 of the Amendment Under 37 C.F.R. § 1.111 filed January 5, 2006.

The following error is apparently the fault of the Inventor:

At column 16, line 5 (claim 11, line 21) of the printed patent, "move" should be ---moved---. This appeared incorrectly on page 6, line 5 of the Amendment Under 37 C.F.R. § 1.111 filed January 5, 2006.

Therefore, it is respectfully requested that a Certificate of Correction issue in the above-identified patent as follows:

At column 16, line 8 (claim 12, line 3) of the printed patent, "1/2," should be ---1/2)---.

At column 16, line 61 (claim 16, line 19) of the printed patent, "iniECTION" should be ---injection---.

At column 16, line 5 (claim 11, line 21) of the printed patent, "move" should be ---moved---.

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,
S. H. VOLDMAN

A handwritten signature in black ink, appearing to read 'Andrew M. Calderon', written over a horizontal line.

Andrew M. Calderon
Reg. No. 38,093

January 26, 2007
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,089,520
APPLICATION NO.: 10/707,069
ISSUE DATE : August 8, 2006
INVENTOR(S) : S. H. VOLDMAN

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 16, line 8 (claim 12, line 3) of the printed patent, "1/2," should be ---1/2)---.

At column 16, line 61 (claim 16, line 19) of the printed patent, "injection" should be ---injection---.

At column 16, line 5 (claim 11, line 21) of the printed patent, "move" should be ---moved---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

1950 Roland Clarke Place
Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.